

FILE COPY

O T T A W A

December 30th, 1941.

R E P O R T

of the

ORE DRESSING AND METALLURGICAL LABORATORIES.

Investigation No. 1142.

Examination of a Defective Strut  
Attachment from a Stranraer Aircraft.

DP

(Copy No. 9.)

This document was produced  
by scanning the original publication.

Ce document est le produit d'une  
numérisation par balayage  
de la publication originale.

2581



O T T A W A

December 30th, 1941.

R E P O R T  
of the  
ORE DRESSING AND METALLURGICAL LABORATORIES.

Investigation No. 1142.

Examination of a Defective Strut  
Attachment from a Stranraer Aircraft.

=====

Origin of Material and Object of Investigation:


On December 10th, 1941, Flight Lieutenant A. J. Smith, of the Department of National Defence (Air Services), Ottawa, Ontario, submitted a broken lug, tail-plane strut No. 23018-229, for examination. In an accompanying letter, from Group Captain A. I. Johnson, for Chief of the Air Staff, (File No. 1021-20-11 (AMAE DAI)), it was stated that Specification S.80 - High Chromium

(Origin of Material and Object of Investigation, cont'd) -

Steel - governs in regard to the material. It was requested that the part be examined for strength characteristics and also be analysed metallurgically.


The broken part as received is shown in Figures 1 and 2 (top and side views).

Figure 1.



BROKEN  
LUG  
AS  
RECEIVED.  
(Approximately  
 $\frac{3}{4}$  size)

Figure 2.



Chemical Analysis:

	<u>Defective Strut.</u>	<u>Specification S.80</u>
Carbon, per cent	0.16	Not more than 0.25.
Manganese, "	0.95	" " " 1.00.
Silicon, "	0.36	" " " 0.50.
Chromium, "	16.95	Between 16.0 and 20.0.
Nickel, "	2.29	Not less than 1.00.

Hardness Tests:

The Vickers hardness tester was used.

Defective Strut

290 V.H.N.

Specification S.80

Not less than 241 (Brinell)

The Vickers and Brinell hardness values are practically identical up to a hardness of about 300.


Tensile Tests:

Two test pieces were obtained from the submitted specimen and were tested on a TENSOMETER testing machine. The results obtained by testing these small pieces are comparable, although perhaps not identical, with the standard-sized test pieces.

	<u>No. 1.</u>	<u>No. 2.</u>	<u>Spec. S.80</u>
Gauge length	-	0.400 inch.	
Gross-sectional area	-	0.02342 sq. in.	
Elastic limit, p.s.i. -	103,500	103,500	
12.5 per cent proof (load at 0.050 in. permanent set), p.s.i. -	116,000	120,500	
Ultimate strength, p.s.i. -	133,500	133,500	123,000 min.
Elongation, per cent -	10%	20%	15% minimum.
Reduction of area, per cent -	20%	35.5%	

Macrographic Examination:


Figure 3.



Section of Broken Lug,  
after etch in 1:1 HCl.

Microscopic Examination:

Figure 4.



X500, etched in  
ferric chloride and HCl aqueous  
solution.

Remarks:

The use of a miniature-size test piece was unavoidable, owing to the small size of the sample. From the two physical tests it is probable that the original material met physical as well as chemical requirements of Specification S.80.

The microstructure shows the three phases typical of heat-treated stainless steel of the 17 per cent chromium 2 per cent nickel type, with the banded structure produced by rolling and/or forging.

Cause of Failure:

The fracture has the typical smooth "oyster shell" surface which is characteristic of fatigue fractures. A point to be noted is that machining marks run parallel to the path of the fracture. Since the metal did not appear to deviate from the specification S.80, it must be concluded that in service repeated alternating stresses were imposed upon the lug which were not anticipated in the design of the aircraft.

Discussion and Recommendations:

With this type of metal the impact strength drops rapidly as hardness increases above 250 B.H.N. The following results are quoted from the Atlas Steels Limited catalogue:

(Continued on next page)

(Discussion and Recommendation, cont'd) -

Mechanical Properties, 1-inch Rod -  
(Oil-quenched from 1750° F. and drawn for 1 hour)

Draw	Tensile strength, : p.s.i.	YIELD, : p.s.i.	Elonga- : tion, : per cent	Reduction: : of area, : per cent	Izod	B.H.N.
800°F.	205,000	178,000	15	48	10	387
1000°F.	175,000	163,000	17	51	12	332
1200°F.	137,000	117,000	21	55	47	255

It is to be noted that a B.H.N. of 290 is in the borderline zone between high and low impact strength. It would be desirable to maintain the hardness of this part within 240 to 270 B.H.N. and to avoid the use of draw temperatures between 800° F. and 1100° F.

It was noted that the fracture occurred at right angles to the rolling direction. This would be expected to be the weakest plane in the metal.

It is therefore suggested that:

- (1) Transverse and longitudinal test pieces be prepared and tested to determine the difference in properties, if any.
- (2) If the metal is weaker transversely the lug should be re-oriented to make use of the greatest strength of the material.

More specific recommendations could be made if more material were available for examination. This would

(Discussion and Recommendation, cont'd) -

make it possible to determine the exact relationship between hardness and physical properties for this metal, and also the transverse strength could be compared with the longitudinal strength.

ooooooooooooo  
ooooooo  
o

HHF:PES.



GOVT. OFF. CANADA  
BOND