

OTTAWA April 15th, 1942.

# REPORT

of the

ORE DRESSING AND METALLURGICAL LABORATORIES.

Investigation No. 1203.

Investigation of a Dominion Foundries and Steel Limited Towing Hook.

BUREAU OF MINES
DIVISION OF METALLIC MINERALS
ORE DRESSING AND
METALLURCICAL LABORATORIES



O T T A W A April 15th, 1942.

#### REPORT

of the

#### ORE DRESSING AND METALLURGICAL LABORATORIES.

Investigation No. 1203.

Investigation of a Dominion Foundries and Steel Limited Towing Hook.

many amount the drape quests drape about about residence of the residence


#### Origin of Request:

On April 1st, 1942, under Analysis Requisition
No. O.T. 220, Mr. R. Boult, of the Inspection Board of the
United Kingdom and Canada, 58 Lyon Street, Ottawa, Ontario,
submitted a towing hook for examination. This hook was
cast by the Dominion Foundries and Steel Limited, Hamilton,
Ontario, from Heat No. 3668. An X-ray examination was
requested. The chemical analysis, physical properties, and
microstructure were also checked.

#### Macro-Examination:

The base of the casting submitted for examination was badly pitted. This is shown in Figure 1.

### Figure 1:



PHOTOGRAPH OF BASE OF TOWING HOOK. (About & size).

# Note pits.

#### X-Ray Examination:

X-ray examination was carried out at the National Research Council, Ottawa. This examination did not disclose any unsoundness.

#### Physical Tests:

A tensile bar 0.282 inch diameter was obtained for physical testing. The results of this test are given in Table I.

#### Table I. - Physical Tests.

		Obtained	Spe	cified
Tensile strength, p.s.i. Yield strength, p.s.i. Elongation in 1 inch, per cent Reduction in area, per cent Vickers Pyramid No.	99 69	86,400 57,600 27 29,4 169	78,000 40,000	to 90,000 min.

## Chemical Analysis:


The chemical analysis of the metal in the hook is as follows:

		Per cent
Carbon		0.30
Manganese	400	0.73
Silicon	Mak	0.44
Sulphur	esto	0.032
Phosphorus	-	0.021

## Microscopic Examination:

The microstructure of the metal in this hook is illustrated in Figure 2. It is quite normal.

#### Figure 2.



X100, nital etch.
PHOTOMICROGRAPH.

#### Discussion of Results:

The physical specifications have been met and the microstructure indicates proper heat treatment practice. Evidently the method of moulding is correct since the X-ray failed to reveal any unsoundness.

The appearance of the casting, however, leaves much to be desired. It would indicate that their might be some carelessness in moulding or pouring. While in this case it (Discussion of Results, cont'd) -

did not affect the quality of the casting, there is always greater risk of producing defective castings when such conditions exist.

# Conclusions:

- 1. The casting is sound.
- 2. The physical specifications were met.
- 3. Heat treatment practice was correct.

0000000000

HVK:GHB.

