# FILE COPY

OTTAVA

July 23rd, 1942.

REPORT

of the

ORE DRESSING AND METALLURGICAL LABORATORIES.

Investigation No. 1268.

Examination of Two Failed Austenitic Manganese Steel Castings.

State April 1277 & workering and a teach a track to the regard of and Lancel Co. 11 Teach and the State. Cond. Cond. Principal April 1277 & April 1277 Princip and a recity by the Princip of Co. 2 December 1277 Co. 1277 Princip and Princip and Color and April 2 December 1277 Princip and Princip and Color and Color and April 2 December 1277 Princip and Princip and Color and Color and April 2 December 1277 Princip and April 2 December 1277 Princip and Color a CANADA

BUREAU OF MINES
DIVISION OF METALLIC MINERALS

ORE DRESSING AND METALLURGICAL LABORATORIES

DEPARTMENT ,
OF
MINES AND RESOURCES
MINES AND GEOLOGY BRANCH

AWATTO

July 23rd, 1942.

REPORT

of the

ORE DRESSING AND METALLURGICAL LABORATORIES.

Investigation No. 1268.

Examination of Two Failed Austenitic Manganese Steel Castings.

delta depoisit des en contro deltas que se applica que a esta espara en especia deltas que se applica que se especial del que en especia deltas que se applica

#### Source of Material and Object of Investigation:

On July 9th, 1942, Mr. J. A. Sutherland, Sales
Department, JOLIETTE STEEL LIMITED, Joliette, Quebec, submitted
sections of two manganese steel castings for examination.

It was stated, in a letter dated June 27th, 1942, that these
castings, a jaw plate and a dipper tooth, had failed in
service at the plant of the International Nickel Company of
Canada Limited, Copper Cliff, Ontario. It was also stated

(Source of Material and Object of Investigation, cont'd) that chemical, physical and microscopic tests carried out
by different laboratories were not conclusive. A complete


examination by our laboratories was therefore desired in order to clear up, if possible, the cause of these failures.

In this report, the jaw plate and dipper tooth castings will be referred to as Steel No. 1 and Steel No. 2, respectively.

#### Macro-Examination:

Figures 1 and 2 show the fractures of the two castings.

#### Figure 1.



JAW PLATE FRACTURE.

(Approx. 1/3 size).

Figure 2.



DIPPER TOOTH FRACTURE.

(Approx. 1/3 size).

#### Chemical Analysis:

12. 12. 12. 1	G12	(P	0	x	C	0	IJ		a;)
---------------	-----	----	---	---	---	---	----	--	-----

But But Spife Ash South Level Spirited Provider Africa & Highly Confederate In Million South	्रे <i>र होच्या</i> व्यक्ताहरी होते. वर्षः ३५ हो	A.S.T.M. Spec. A 128-33.	Steel No. 1.	Stool Southern
Carbon	Mise	1.00-1.40	1.32	1.23
Manganese	e7s	10.00-14.00	15.22	11.34
Silicon	रत्य	0.25-1.00	0.55	0.88
Phosphorus	ç.a	0.10 max.	0.071	0.074
Sulphur	468	0.05 max.	0.010	0.010
Chromium	E.10	फा €३	0.13	0.13

#### Microscopic Examination:

Both steels were found to be fairly clean. Figures 3 and 4 are photomicrographs at X100 magnification of Steels Nos. 1 and 2 respectively, after an etch in a solution of 4 per cent picric acid in alcohol. Figures 5 and 6 are photomicrographs of the same steels at X1000 magnification, also etched in picral. Figure 7 shows, at X100 magnification, the structure of Steel No. 1. Both steels contain massive free carbides (the white etching constituent) along the grain boundaries and also within the grains.

# (Figures 3 to 7 are at back of this report)

#### Discussion of Results:

The compositions of the two steels were found to be within the limits of the S.S.T.M. specification for austenitic manganese steel, except for the manganese content of Steel No. 1. Both steels were fairly clean and, apart from the high manganese content in Steel No. 1, appeared to have been properly made. The small grain size of the steels indicates

(Discussion of Results, cont'd) -

that the steel was not poured from too high a temperature.

The presence of free carbides in these castings, especially along the grain boundaries, would have an embrittling effect and consequently would lower their impact physical properties.

In order to get these carbides in solution the casting must be heated to the proper solution temperature and to retain them in solution the casting must be quenched rapidly in cold water. It may be that the quenching temperature was too low or that the quenching rate was not fast enough.

#### Conclusions:

The failure of the castings can be attributed to the embrittling effect of the free carbides at the grain boundaries.

The presence of these carbides in the steel was due to a faulty heat treatment.

00000000000

0

# (Photomicrographs)

#### Figure 3.

### Figure 4.



X100, picral etch. STEEL NO. 1.



X100, picral etch. STEEL NO. 2.


## Figure 5.



X1000, pieral etch. STEEL NO. 1.

# (Photomicrographs, cont'd) -

# Figure 6.



X1000, picral etch. STEEL NO. 2.

# Figure 7.



X100, picral etch. MICROSTRUCTURE OF STEEL NO. 1.

PLTM ettelle attelle occupe findine filtette statue attelle occupe, access decide filmette nyelle approximate attelle vision filmen. Streny dipute accept filmen filmette occupe occupe statue, accept accept filmen. Mentre statue accept filtette vision filmette vision filmette.