

OTTAWA December 30th, 1942.

REPORT

of the

ORE DRESSING AND METALLURGICAL LABORATORIES.

Investigation No. 1339.

Examination of Manganese Steel Crusher Jaw Plates from the Sorel Steel Foundries Limited, Sorel, Quebec.

(Copy No. 10.)



BURFALL OF MINES DIVISION OF METALLIC MINERALS ORE DRESSING AND METAILURGICAL LABORATORIES

DEPARTMENT OF

MINES AND RESOURCES MINES AND GEOLOGY BRANCH

AWATT OZE x 18"

December 30th, 1942.

analysed. The reaults follow:

- 30	ieo re	- <u>P</u>			
.1		1.09			
a Sal		12,38			
.0.		0.049			
.0		0,013			
			R	14	P

ORT of the

ORE DRESSING AND METALLURGICAL LABORATORIES. e plates broke with a britila, crystalline

from the surface into the interior of the cestings.

Examination of Manganese Steel Crusher Jaw bedallog anyPlates from the SoreloSteel Foundries Limited, Sorel, Quebec. anonioega dois , bies sintin interio acid, Both speciaens

contained large shounds and a second or present as patches

This is illustrated in Figures I and 2.

Origin of Samples:

On December 21st, 1942, Mr. J. R. Blais, of the Sales Department, Sorel Steel Foundries Limited, Sorel, Quebec, submitted two samples, one marked "24 x 15" and the other "20 x 10", cut from manganese steel crusher jaw plates which had failed after five and four days, respectively, in the service of the Canadian Carborandum Company 108:01 Object of Study:

Request was made for chemical analysis of the samples and investigation of the microstructures, in order to determine, if possible, the cause of failure.

- Page 2 -

Chemical Analysis:

3th. 1942.

Drillings from the castings were chemically analysed. The results follow:

December 3(AWAT	T 024 x 15"	"20 x 10"	
		- Per cent -		
Carbon	-	1.09	1.12	
Manganese	-	12.38	12.40	
Silicon	-	1,20	0.63	
Phosphorus -		0.049	0.062	
Sulphur	-	0.013	0.007	
	PORT	RB		

0117 10

ORL DERSSING AND MATALLURGICAL

Macro-Examination:

The plates broke with a brittle, crystalline fracture. Pores upito about 1/8-inchidismeter, most noticeable in the "20 x 10" crusher plate, extended back from the surface into the interior of the castings.

Microstructure:

Wal redained leeds esencenes to not the plates was polished obcourded the plates was polished bedown level the plates was polished bedown level the plates was polished bedown level the plates was polished obcourd the second the second the second as a network around the grain boundaries. This is illustrated in Figures 1 and 2.

Many globular inclusions, thought to be oxide, were discovered in both samples. The largest, found in the "20 x 10" plate, was approximately 0.018 inch in diameter. A shrinkage cavity discovered in the "20 x 10" plate is shown, was noted to be a state of the state

Discussion of Results on Canadian Cartastate and at

The porosity in the plates was caused by faulty casting technique. These pores would weaken the parts and for this reason may have contributed to their failure. The globular inclusions and the small shrink present in the castings are defects of minor importance.

In the "24 x 15" plate the silicon is rather high, but since the sample has not an excessive amount of silicate inclusions this is thought to be practically harmless.

The greatest single cause of failure is certainly the large amount of free carbide present, because manganese steel develops its well-known toughness only when all the carbon is in solution.

The free carbides present were caused by one or more of the following:

- 1. A quench from too low a temperature.
- 2. Insufficient soaking time at the correct temperature.
- 3. A quench that was not drastic enough, or one in which some delay occurred.

LPT:LB.

Figure 1.



X1000, nital etch. "24 x 15" CRUSHER JAW PLATE.



X1000, nital stch. "20 x 10" CRUSHER JAW PLATE.

Ł

Figure 2.

- Page 5 -

Figure 3.



X100, unetched: SHRINK IN "20 x 10" PLATE.

> unter effet, surs entre contra error contra anno matta conta error contra filmo error effet, error filmo contra filmo error conta error er conta

LPT:LB,

1

1

,