

01-79875000.2

CPUB

Title
Page

MRL 89-013 (TR) C.2

VIDEO PROBE INSPECTION OF ROOFBOLT HOLES
AT KIDD CREEK MINE

G. Herget and B. Arjang

MRL 89-13 (TR) C.2

CPUB

FEBRUARY 1989

MRL 89-013 (TR) C.2

[Faint, illegible text, possibly bleed-through from the reverse side of the page]

MRJ 81013 (TR) C.S

MRJ 810-98. 39M

Canmet Information
Centre
D'information de Canmet

JAN 29 1997

555, rue Booth ST.
Ottawa, Ontario K1A 0G1

1-M987500c.2
CPUB

VIDEO PROBE INSPECTION OF ROOFBOLT HOLES
AT KIDD CREEK MINE

by

G. Herget* and B. Arjang*

SUMMARY

Sixty-three roofbolt holes have been inspected with a colour video probe and recorded on videotape at the Kidd Creek mine of Falconbridge Ltd. The records are needed as a background document for the description for an in-situ trial on the Swellex roof support system. The test site at the Kidd Creek mine is located on 2500 level at the 2526 stope undercut and the holes were drilled in the week of January 16-20, 1989. The hole inspection was carried out on January 24 and 25, 1989. The rock mass consists of massive sulfides with only a few holes showing geological discontinuities.

A slight concentration of cracks occurs about 1.2 m to 1.6 m from the collar. On viewing the video tape the observer needs to consider that the linear magnification is about fivefold and the real magnification is 28-fold. The rock mass can be classified as good to very good.

KEYWORDS: Video borehole inspection, borehole surveys, roof support.

* Research Scientists, Canadian Mine Technology Laboratory, Elliot Lake Laboratory Mining Research Laboratories, CANMET, Energy, Mines and Resources Canada, Ottawa, Ontario.

0.2
CPUB

INSPECTION PAR SONDE VIDÉO DE TROUS DE BOULONS D'ANCRAGE
À LA MINE KIDD CREEK

par

G. Herget* et B. Arjang*

SOMMAIRE

Soixante-trois trous de boulons d'ancrage ont été inspectés avec une sonde vidéo couleur et les données ont été enregistrées sur bande vidéo à la mine Kidd Creek de la Falconbridge Ltée. Les données enregistrées servent de document de base pour décrire un essai in situ du système de soutènement Swellex. Le lieu d'essai à la mine Kidd Creek est situé sur le niveau 2 500 au havage en galerie 2 526 et les trous ont été forés pendant la semaine du 16 au 20 novembre 1989. Le massif rocheux est composé de sulfures où des discordances géologiques n'ont été révélées que par quelques trous.

Une faible concentration de fissures se trouve entre 1,2 et 1,6 m environ, de l'orifice. En visionnant l'enregistrement vidéo, il faut tenir compte du fait que le grossissement linéaire est d'environ cinq et que le grossissement réel est de 28. Le massif rocheux peut être classé de bon à très bon.

MOTS-CLÉS: inspection des trous par sonde vidéo; examen des trous de sonde; soutènement du toit.

* Chercheurs scientifiques, Laboratoire canadien de technologie minière, Laboratoires de recherche minière d'Elliot Lake, CANMET, Énergie, Mines et Ressources Canada, Ottawa (Ontario)

CONTENTS

	<u>Page</u>
SUMMARY	i
SOMMAIRE	ii
INTRODUCTION	1
VIDEO EQUIPMENT	1
BOREHOLE INSPECTION	2
CONCLUSIONS	6
REFERENCES	6
ACKNOWLEDGEMENTS	6

FIGURES

<u>No.</u>		<u>Page</u>
1.	Borehole inspection equipment at Kidd Creek mine	7
2.	2500 level mine openings	8
3.	Borehole location	9
4.	Borehole identification	10
5.	Geology of Swellex test site on 2500 level	11
6.	Logging sheet	12

TABLES

<u>No.</u>		<u>Page</u>
1.	Swellex Borehole Inspection Summary for Kidd Creek Mine 2526 Stope U/C (Video tape Nr. 1)	4

INTRODUCTION

On request by the Nickel Development Institute, Toronto a borehole survey was carried out with a colour video probe and recorded on tape at the Kidd Creek mine of Falconbridge Ltd. near Timmins, Ontario (1). The 63 holes are 1.8 m deep, have a diameter of 38.1 mm and are located on 2500 level. The 2526 stope undercut is located in massive sulfides which are composed primarily of pyrite, sphalerite, chalcopyrite, galena and pyrrhotite (2). The mining method for the Kidd Creek orebody is blasthole stoping with delayed rock fill (3).

The video survey was conducted to provide background information for an in-situ test of the stainless steel Swellex roof support system at a number of mine sites.

VIDEO EQUIPMENT

The video borehole inspection equipment consisted of a Video Probe V1635-50 (\$US 23,700), a video processor V1678 (VPII 1 colour/LED - \$US 13,400), a monitor V1572 (colour 13" RGB/Composite Panasonic #MT1340 - \$US 890), a keyboard V1504II - \$US 600) and a Lloyds VCR (Fig. 1).

The video probe 2000 system is manufactured by Welch Allyn, Inc., Video Division, State Street Road, Box 220, Skaneateles Falls, NY, 13153-0220, phone (315) 685-4599. The Canadian representative is Flolite Industries, 8 Ripley Avenue, Toronto, Ontario, M6S 3N9, phone (416) 767-2755.

The equipment was obtained on loan from INCO Ltd., Copper Cliff, Ontario.

The video probe has a length of 15.4 m (50 ft) and the O.D. of the camera head and cable are 10.2 mm (0.402 in.). The probe provides an axial view but can be equipped with a side viewing attachment. The image on the monitor can be complemented by written comments through keyboard

entries (three pages maximum) or by spoken comments with the aid of a microphone. The illumination is controlled by an automatic level controller which is very effective in finding optimum illumination levels.

For the vertical holes the video probe was led through aluminum rods and tied to the top with electricians tape. This protected the cable and allowed rotation of the video head in the hole. The side viewing attachment was used only once (first hole) because the mirror collected dust very easily and the obtained picture was a composite of axial and side view.

BOREHOLE INSPECTION

The Swellex test site is located on 2500 level in the 2526 stope undercut (Fig. 2). Twenty-one sets of three holes of 38.1 mm diameter (1.5 in.) had been drilled 1.80 m (6 ft) into the roof (Fig. 3). All holes were inspected and a record is available in colour on tape 1. Figure 4 explains the borehole identification which consists of a seven position alphanumeric with the first two identifying the mine (KC = Kidd Creek), the next two the level (25 = 2500 level), the next letter the location (S = South, V = Vertical, N = North) and the last two digits the row number (11 = row number 11). Logging of the individual holes started with row one at the west end and progressed E until row number 21 was reached. In total 63 holes were surveyed.

Figure 5 shows the geology of the site provided by Kidd Creek mine. Nearly all the holes were located in massive sulfides consisting of yellow pyrite (FeS_2) and brown stringers or areas of sphalerite (ZnS). Only occasionally the holes showed quartz veins. All holes were slightly fractured at the collar from blasting. In a number of places the roof required scaling. In total the rock mass is very competent and only occasionally do the borehole walls show small breakouts from micro cracking or some subhorizontal jointing. Only seven holes showed vertical fractures (Table 1).

The video tape starts in all cases at the top of the hole and is lowered slowly to display the axial view of the borehole wall. If anything of interest appeared, the footage was repeated. In some cases a complete run was made from the collar upwards. The video head was rotated back and forth to achieve better light distribution in the hole. Half way down the hole the video display often shakes because one rod is unscrewed to allow rod clearance for retraction.

A logging sheet was prepared for each hole (Fig. 6) but they are not reproduced in this report. Table 1 contains the information on the logging sheets in a condensed format. If the videotape counter is set to zero at the start of the tape, the locations for the individual holes is easily found with the aid of Table 1.

TABLE 1 - Swellex Borehole Inspection Summary for Kidd Creek
Mine 2526 Stope U/C (Video tape Nr. 1)





TABLE 1 (cont'd)



- 2) rough wall of collar
 3) (2 runs), back of hole cracked (1724)
 4) breakouts
 5) rough wall

CONCLUSIONS

The video probe inspection showed that the rock mass at the site consists of massive sulfides varying in composition from bright yellow pyrite (FeS_2) to light brown sphalerite (ZnS).

Nearly all holes had some fracturation close to the collar. Only a few holes displayed intersections of subhorizontal and vertical discontinuities.

The video camera system is bulky to move about and needs to be operated in a dry environment. The picture quality is excellent. The illumination could be improved by centering the camera head in the hole and more distortion free detail could be observed by improving the right angle viewing attachment.

ACKNOWLEDGEMENTS

The authors thank Dr. Thiann R. Yu, Chief engineer of R&D Productivity - Mining, for the effective scheduling and help provided at the Kidd Creek mine site.

The authors are also indebted to INCO Ltd., Sudbury, who made the video equipment available.

REFERENCES

1. Clarke, R. "Mining Research Laboratories' proposal for field evaluation of stainless steel Swellex bolts"; November, 1988.
2. Matulich, A., Amos, A.C., Walker, R.R. and Watkins, J.J. "The Ecstall story - Regional geological setting and mine geology"; p. 56-62, CIM Bulletin, May, 1984.
3. Yu, Th.R., Quesnel, W.J. "Applied rock mechanics for blasthole stoping at Kidd Creek mines"; Geomechanics Applications in Underground Hard Rock Mining, Editor W.G. Pariseau, p. 93-107, AIME, 1984.



Fig. 1 - Borehole inspection equipment at Kidd Creek mine

This sheet is supplied for preparing master sheets for reproduction of paper or metal offset plates by "Xerox" or photography. All material to be reproduced (typed, drawn or mounted) is to be kept within the blue boundary lines.

SINCE THE ORIGINAL TYPED COPY IS TO BE PHOTOGRAPHED, PLEASE WRITE ANY PROPOSED REVISIONS ON THE CARBON COPY ONLY

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48




Fig. 2 - 2500 level mine openings

This data is supplied for information only. It does not constitute a warranty or a statement of fact. It is the user's responsibility to verify the accuracy of the data. The user is advised to consult the original data source for more information.

THE ABOVE INFORMATION IS UNCLASSIFIED EXCEPT WHERE SHOWN OTHERWISE. IT IS THE PROPERTY OF THE U.S. GOVERNMENT AND IS LOANED TO YOUR AGENCY. IT AND ITS CONTENTS ARE NOT TO BE DISTRIBUTED OUTSIDE YOUR AGENCY.




Fig. 3 - Borehole location

SWELLEX TESTING


ALL RINGS ARE DRILLED WITH 4' SPACING RING TO RING 21

SECTION LOOKING EAST

214,400N

8,400'

214,300N



2526 STOPE **u/c**

HOLE	DUMP	DIP	DEPTH	DRILLED	COMMENT
1	-90°	+58°N	6'		
2	-90°	+90°	6'		
3	-90°	+62°S	6'		
TOTAL			8'		

Holes are identified by a 7 digit alpha-numeric

e.g. K C 25 V II

Kidd Creek

2500 Level

Vertical Hole

Section II

Fig. 4 - Borehole identification

214,400

215,900 E




Fig. 5 - Geology of Swellex test site on 2500 level

Hole Identification:

Date:

Operator:

(Identification consists of a seven position alphanumeric: 2 letters for mine, e.g. Kidd Creek=KD; 2 digits for level, e.g. 2800 level=28; 3 digits for hole number, e.g. hole nr. 1=001)

Collar position and hole orientation:
(e.g. east wall 60 degrees up)

Diameter:

Trend:

Plunge:

OBSERVATIONS

Roof appearance: stable, sagging, minor spalling, fractured

Rock mass: massive, bedded, jointed - sprayed

Rock type at collar:

Bore hole wall inspection:

depth from	!	rock type, colour, fractures, angle of
collar(m)	!	intercept, open or filled joints

Photograph:

Number of discontinuities/m:

Core recovery:

RQD:

Remarks: additional records, video tape location, core logs

Fig. 6 - Logging sheet

