

Figure 33. Thickness map of the Syntectonic Unit of the HB Assemblage, assuming a seismic interval velocity of 5800 m/s. Contour interval is 1000 m. Fault pattern within basement outcrop area is after Hoffman (1984) and St-Onge et al. (1991).