Natural Resources Canada | Ressources naturelles Canada
Fisheries and Oceans Canada | Pêches et Océans Canada
GEOLOGICAL SURVEY OF CANADA | COMMISSION GÉOLOGIQUE DU CANADA


Figure 1. Sun-illuminated seafloor topography of Baddeck–St. Patricks Channel
This image is based on a 2-m grid of the data, and shows part of St. Patricks Channel, near Baddeck. The image reveals terrestrial environments on the seafloor that existed before ca. 6000 BP, and that were flooded by the rising sea level during the Holocene. Channel meanders, oxbow lakes and ponds are all features that are buried in mud that ranges up to 3 m in thickness. Careful examination of the image reveals a former ox-bow lake. Sediment cores that penetrated the mud intersected peat layers formed in swamp and marsh environments. This has provided further evidence of the sluggish drainage on the ancient valley floor. Further east the ancient river valley is incised into glacial deposits, forming a series of steep bluffs. The narrow valley floor contains the deepest water, and numerous pockmarks (craters) that are probably indications of a gravelly river bed. The ancient river entered the lake just beyond the coverage of this image.
Sinkholes are common in Great Bras d'Or, but rare in St. Patricks Channel, probably because of the considerable thickness of Quaternary sediments; however, there are a few isolated sinkholes in St. Patricks Channel, including an example just east of Campbells Cove (main map) and a cluster of three sinkholes at Hermitage Cove, on the eastern shore of the lake (see inset in this figure). Careful examination of this high-resolution image also reveals features not evident on the 10 m gridded imagery of the entire region, including dredge-spoil heaps, anchor-dragmarks, and tread-board marks.
Depth (m)
2
5
10
15
20
25
30
0
1
kilometres
Baddeck
Crescent Grove
Big Farm
Harris Pool
Islets Baddeck
St. Patricks Channel
Kidston Island
Thrasher Point
Red Head
Bone Island
Spectacle Island
Nail Island
Grey Point
MacKay Point
Lower Wasbabuck
Burnt Point
Murphy Point
Wasbabuck Centre
Big Barren
Little Barren
Spotted Mountain
Crowdis Mountain
Big Hill
Baddeck River
Bason Brook
Figure 1
LAKE AINSLIE
Northside Mountain
Whycocomagh Mountain
Calins Mountain
Whycocomagh
Whycocomagh Basin
Whycocomagh Village
Grand Narrows
Kelly's Mountain
Bras d'Or
Great Bras d'Or
St. Andrews Channel
Boisdale Hills
Boisdale Bridge
Blueberry Barren
Mount Cameron
Sydney Forks
Point Edward
North West Arm
Sydney Harbour
Coxheath Hills
Boisdale Lakes
Mt. Cameron Lakes
Coxheath Lakes
Mt. Cameron Barrens
Coxheath Barrens
Mt. Cameron Marsh
Coxheath Marsh
Mt. Cameron Brook
Coxheath Brook
Mt. Cameron Pond
Coxheath Pond
Mt. Cameron Point
Coxheath Point
Mt. Cameron Cove
Coxheath Cove
Mt. Cameron Island
Coxheath Island
Mt. Cameron Mountain
Coxheath Mountain
Mt. Cameron Creek
Coxheath Creek
Mt. Cameron Bridge
Coxheath Bridge
Mt. Cameron Village
Coxheath Village
Mt. Cameron Harbour
Coxheath Harbour
Mt. Cameron Road
Coxheath Road
Mt. Cameron Hills
Coxheath Hills
Mt. Cameron Lake
Coxheath Lake