GEOLOGICAL SURVEY OF CANADA
DEPARTMENT OF MINES AND TECHNICAL SURVEYS

LEGEND

- Bedding, inclined
- Joint with spacing, inclined, vertical
- Fault, downthrow side, stratigraphic separation, pitch of striae
- Slickenside striae on bedding
- Crack irregular, with dip
- Timber, x-member, broken
- Entry ribs
- Roof bolt, bolt out
- Extensometer
- Strain gauge
- Drill rod stuck in hole
- Noticeable seepage from cracks
- Photo location with direction
- Roof scaled prior to placing artificial supports
- Roof completely lagged
- Roof collapsed after placing artificial supports
- Interval with open cracks

Geology by D. K. Norris, November, 1963
To accompany Paper 64-24 by D. K. Norris

Published, 1965

Printed by the Surveys and Mapping Branch

Figure 3. Geological sketch-plan of roof, test entry, A-North Mine, Michel, British Columbia

This document was produced by scanning the original publication.

Ce document est le produit d'une numérisation par balayage de la publication originale.